

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/4	MAKE	HITACHI	MODEL	EX120-5
SERIAL	1E4-51920			STAMP	1E4-51920
HR METER	9556	HR	YEAR	1997	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	500G

ENGINE : MODEL		S/N
Oil leakage	FAIR • <u>Attn</u> *1	
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn	
Oil	FAIR • Attn	
Exhaust Color	FAIR • Attn	
US EPA	YES • <u>NO</u>	
MAIN PUMP		
Sound	FAIR • Attn	
Oil leakage	FAIR • Attn	
Power	FAIR • Attn	
COOLING SYSTEM		
Radiator	FAIR • Attn	ファンベルトひび割れあり FAN BELTS: CRACKED
Oil Cooler	FAIR • Attn	
OPERATING SYSTEM		
Swing	FAIR • Attn	ガタあり SWING: LOOSE
Travel	FAIR • Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • <u>FAIR</u> • DIRTY	
Operator's Seat	FAIR • Attn	
Glasses	FAIR • Attn	
AirCon	<u>A/C</u> • H/C • H only • C only • None	
BOOM / ARM / BKT		
Boom	FAIR • Attn	
Boom Cylinder	FAIR • <u>Attn</u>	左右にじみあり CYLINDERS: OIL OOZING
Arm	FAIR • Attn	
Arm Cylinder	FAIR • Attn	
ATTACHMENT	FAIR • Attn	
BKT Cylinder	FAIR • <u>Attn</u>	油漏れ小 OIL LEAKING

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
スイベル下油漏れ小 BOTTOM OF SWIVEL: OIL LEAKING	
左右トラックローラーガタあり SOME TRACK ROLLERS: LOOSE	
左キャリアローラー曲がりあり LEFT CARRIER ROLLER: BENT	
BKT (<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ())	
Lever	LONG • <u>WRIST</u>
Multi	MULTI • 2 • <u>NO</u>
ARM-CRANE	<u>YES</u> • NO ユニット電源入らない UNIT: UNABLE TO TURN ON
BLADE	YES • <u>NO</u>
OFFSET	YES • <u>NO</u>
OFFSET Cylinder	FAIR • Attn
Piping	YES • <u>NO</u> Breaker only • Multi
COMMENT	
ブーム背面ホース破れあり	
SOME HOSE AROUND BOOM: A LITTLE DAMAGED	
A/C電源入らない A/C: UNABLE TO TURN ON	
*1 配管、E/Gヘッド周りにじみあり	
*1 SOME PIPE & AROUND CYLINDER HEAD: OIL OOZING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。