

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/8/25	MAKE	TADANO	MODEL	TR-250M-6
SERIAL No.	PLATE : FB2090		STAMP : TR255-0618		
HR METER	6884	HR	Odometer	143965	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) (Attn)	A LITTLE · MIDDLE · (SEVERE)
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) (Attn)	白煙あり WHITE FUMES
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
OPERATING SYSTEM		
Computer	(OK) · NG	
Swing	(FAIR) · Attn	
Travel	(FAIR) · Attn	
TRANSMISSION		
Transmission	(FAIR) · Attn	
No. OF GEARS	4	GEARS
4WD	(4WD) · 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) ·	DIRTY
Operator's Seat	(FAIR) · Attn	破れあり HOLES
Glasses	(FAIR) · Attn	
AirCon	(A/C) · H/C · H only · C only · None	
COMMENT		

BOOM				
No. of Section	5		SECTIONS	
CRACK/ENFORCEMENT	FAIR	▪	Attn	
DERRICKING CYL.	FAIR	▪	Attn	
EXTENSION CYL.	FAIR	▪	Attn	
JIB	YES	▪	NO	
JIB TYPE	STD	▪	PWR	
MAIN & SUB WIRE	YES	▪	NO	
FREE FALL	YES	▪	NO	
HOOK	25t, BALL			
UNDERCARRIAGE : See Photos. 写真参照				
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				3
TIRE WEAR	FAIR WORN UNEVEN WEAR			
COMMENT				
右Rタイヤ側面亀裂あり REAR RIGHT TIRE SIDEWALL: CRACKED				
OUTRIGGERS				
OUTRIGGERS	X	▪	H	
OUTRIGGERS COND.	FAIR	▪	Attn	
Oil leakage (JACK CYL.)	FRONT	L	▪ R	REAR L ▪ R
Oil leakage (SLIDE CYL.)	FRONT	L	▪ R	REAR L ▪ R
COMMENT				
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				
				3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。