

INSPECTION SHEET 検品書  
WHEEL LOADER タイヤショベル

|                 |                                        |      |          |           |                               |
|-----------------|----------------------------------------|------|----------|-----------|-------------------------------|
| INSPECTION DATE | 2026/8/19                              | MAKE | HITACHI  | MODEL     | ZW80-5B                       |
| SERIAL          | RYUNCHA0C00011378                      |      |          | STAMP     | H80-11378                     |
| HR METER        | 3747                                   | HR   | Odometer | 15399     | km                            |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      |          | TIRE SIZE | 17.5/65-20 10PR (SNOW, SPIKE) |
| YEAR            | YR                                     |      |          |           |                               |

|                                                   |                                        |
|---------------------------------------------------|----------------------------------------|
| <b>ENGINE : MODEL</b> TD2.9L4 <b>S/N</b> 11941449 |                                        |
| Oil leakage                                       | FAIR • Attn                            |
| Blow-By                                           | FAIR • Attn A LITTLE • MIDDLE • SEVERE |
| Sound                                             | FAIR • Attn                            |
| Oil                                               | FAIR • Attn                            |
| Exhaust Color                                     | FAIR • Attn                            |
| US EPA                                            | YES • NO                               |
| <b>OPERATION PUMP</b>                             |                                        |
| Sound                                             | FAIR • Attn                            |
| Oil leakage                                       | FAIR • Attn                            |
| Power                                             | FAIR • Attn                            |
| <b>COOLING SYSTEM</b>                             |                                        |
| Radiator                                          | FAIR • Attn                            |
| Oil Cooler                                        | FAIR • Attn                            |
| <b>TRANSMISSION &amp; TRAVEL</b>                  |                                        |
| T/M TYPE                                          | PS • DD                                |
| Transmission                                      | FAIR • Attn                            |
| Travel                                            | FAIR • Attn                            |
| FOOT BRAKE                                        | FAIR • Attn                            |
| PARKING BRAKE                                     | FAIR • Attn                            |
| <b>INTERIOR See Photos. 写真参照</b>                  |                                        |
| INTERIOR COND.                                    | CLEAN • FAIR • DIRTY                   |
| Operator's Seat                                   | FAIR • Attn                            |
| Glasses                                           | FAIR • Attn                            |
| AirCon                                            | A/C • H/C • H only • C only • None     |
| <b>FRONT &amp; CYLINDERS</b>                      |                                        |
| Arm                                               | FAIR • Attn 左右捻じれあり ARMS: DISTORTED    |
| Bell crank                                        | FAIR • Attn                            |
| Bucket                                            | FAIR • Attn                            |
| Articulate                                        | FAIR • Attn                            |

|                                                                      |                                   |
|----------------------------------------------------------------------|-----------------------------------|
| <b>UNDERCARRIAGE : See Photos. 写真参照</b>                              |                                   |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         | 4                                 |
| TIRE WEAR                                                            | FAIR • WORN • UNEVEN WEAR         |
| <b>COMMENT</b>                                                       |                                   |
| STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING     |                                   |
| RIDE CONTROL                                                         | YES • NO                          |
| <b>ATTACHMENTS</b>                                                   |                                   |
| STD BKT                                                              | YES • OTHER                       |
| BLADE                                                                | YES • NO Piping for Tilt YES • NO |
| <b>COMMENT</b>                                                       |                                   |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) |                                   |
| 4                                                                    |                                   |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。