

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/7	MAKE	KOMATSU	MODEL	PC400LC-6E
SERIAL	30027		STAMP	PC400-30027	
HR METER	9324	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	700G	

ENGINE : MODEL		S/N
Oil leakage	FAIR ・ Attn	にじみあり OIL OOOZING
Blow-By	FAIR ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	FAIR ・ Attn	
Oil	FAIR ・ Attn	
Exhaust Color	FAIR ・ Attn	
US EPA	YES ・ NO	
MAIN PUMP		
Sound	FAIR ・ Attn	
Oil leakage	FAIR ・ Attn	油漏れあり OIL LEAKING
Power	FAIR ・ Attn	
COOLING SYSTEM		
Radiator	FAIR ・ Attn	
Oil Cooler	FAIR ・ Attn	
OPERATING SYSTEM		
Swing	FAIR ・ Attn	ガタあり SWING: LOOSE
Travel	FAIR ・ Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ・ FAIR ・ DIRTY	
Operator's Seat	FAIR ・ Attn	破れあり CUTS
Glasses	FAIR ・ Attn	
AirCon	A/C ・ H/C ・ H only ・ C only ・ None	
BOOM / ARM / BKT		
Boom	FAIR ・ Attn	パッチ、ガタあり PATCHED, LOOSE
Boom Cylinder	FAIR ・ Attn	
Arm	FAIR ・ Attn	ガタあり LOOSE
Arm Cylinder	FAIR ・ Attn	
ATTACHMENT	FAIR ・ Attn	
BKT Cylinder	FAIR ・ Attn	

UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
COMMENT					
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER())				
Lever	LONG	▪	(WRIST)		
Multi	MULTI	▪	2	▪	(NO)
ARM-CRANE	YES	▪	(NO)		
BLADE	YES	▪	(NO)		
OFFSET	YES	▪	(NO)		
OFFSET Cylinder	FAIR	▪	Attn		
Piping	YES	▪	(NO)	Breaker only	▪ Multi
COMMENT					
E/Gフード破損あり ENGINE HOOD: A LITTLE DAMAGED					
右サイドカバーラッチ掛からない					
RIGHT SIDE COVER LATCH: MALFUNCTION					
コントロールバルブ油漏れあり CONTROL VALVE: OIL LEAKING					
A/Cベルト欠 A/C: NO BELT					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。