

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/31	MAKE	KOBELCO	MODEL	U-30-5
SERIAL	74668			STAMP	74668
HR METER	2812	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	300R

ENGINE : MODEL		S/N	7CS5092
Oil leakage	FAIR • Attn		
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE	
Sound	FAIR • Attn		
Oil	FAIR • Attn	油量多い HIGH ENGINE OIL LEVEL	
Exhaust Color	FAIR • Attn		
US EPA	YES • NO		
MAIN PUMP			
Sound	FAIR • Attn		
Oil leakage	FAIR • Attn		
Power	FAIR • Attn		
COOLING SYSTEM			
Radiator	FAIR • Attn		
Oil Cooler	FAIR • Attn		
OPERATING SYSTEM			
Swing	FAIR • Attn		
Travel	FAIR • Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN • FAIR • DIRTY		
Operator's Seat	FAIR • Attn	破れあり CUTS	
Glasses	FAIR • Attn		
AirCon	A/C • H/C • H only • C only • None		
BOOM / ARM / BKT			
Boom	FAIR • Attn		
Boom Cylinder	FAIR • Attn		
Arm	FAIR • Attn		
Arm Cylinder	FAIR • Attn		
ATTACHMENT	FAIR • Attn	ガタあり LOOSE	
BKT Cylinder	FAIR • Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG • WRIST
Multi	MULTI • 2 • NO
ARM-CRANE	YES • NO
BLADE	YES • NO
OFFSET	YES • NO
OFFSET Cylinder	FAIR • Attn
Piping	YES • NO Breaker only • Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。