

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/4	MAKE	KUBOTA	MODEL	U-17
SERIAL	22910		STAMP	22910	
HR METER	79	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	230G PADS	

ENGINE : MODEL		D902	S/N	4ES7584
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn	油量多い HIGH ENGINE OIL LEVEL	
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn	*1	
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only
				None
BOOM / ARM / BKT				
Boom	FAIR	Attn	ガタあり LOOSE	
Boom Cylinder	FAIR	Attn		
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn	ガタあり LOOSE	
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4
COMMENT 可変脚仕様 VARIABLE WIDTH UNDERCARRIAGE			
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()		
Lever	LONG • (WRIST)		
Multi	(MULTI) • 2 • NO		
ARM-CRANE	YES • (NO)		
BLADE	(YES) • NO		
OFFSET	YES • (NO)		
OFFSET Cylinder	FAIR • Attn		
Piping	(YES) • NO	Breaker only • (Multi)	
COMMENT ボディリペイントあり BODY: REPAINTED			
*1 左足若干遅い LEFT TRACK: A LITTLE SLOW MOVING			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。