

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/6	MAKE	HITACHI	MODEL	ZX200-5B
SERIAL	HCMDCKA0H00305577		STAMP	HCMDCKA0H00305577	
HR METER	5943	HR	YEAR	YR	
CAB/CNP	☒ ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G PADS	

ENGINE : MODEL		4HK1	S/N	743666
Oil leakage	☒ FAIR · Attn			
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	☒ FAIR · Attn			
Oil	☒ FAIR · Attn			
Exhaust Color	☒ FAIR · Attn			
US EPA	YES · ☒ NO			
MAIN PUMP				
Sound	☒ FAIR · Attn			
Oil leakage	☒ FAIR · Attn	油漏れ小 OIL LEAKING		
Power	☒ FAIR · Attn			
COOLING SYSTEM				
Radiator	☒ FAIR · Attn			
Oil Cooler	☒ FAIR · Attn			
OPERATING SYSTEM				
Swing	☒ FAIR · Attn			
Travel	☒ FAIR · Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	☒ CLEAN ·	FAIR · DIRTY		
Operator's Seat	☒ FAIR · Attn			
Glasses	☒ FAIR · Attn			
AirCon	☒ A/C ·	H/C · H only · C only · None		
BOOM / ARM / BKT				
Boom	☒ FAIR · Attn			
Boom Cylinder	☒ FAIR · Attn			
Arm	☒ FAIR · Attn			
Arm Cylinder	☒ FAIR · Attn			
ATTACHMENT	☒ FAIR · Attn			
BKT Cylinder	☒ FAIR · Attn			

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · ☒ WRIST
Multi	☒ MULTI · 2 · NO
ARM-CRANE	☒ YES · NO *1
BLADE	YES · ☒ NO
OFFSET	YES · ☒ NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · ☒ NO Breaker only · Multi
COMMENT	
E/Gフードヒンジ破損あり ENGINE HOOD HINGES: BROKEN	
*1 半径表示変わらない OPERATING RADIUS: NOT CHANGING TO DISPLAY	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。