

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/8/6	MAKE	CAT	MODEL	972K		
SERIAL	CAT0972KPZ4W00759			STAMP	CAT0972KPZ4W00759		
HR METER	23101	HR	Odometer	73906	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	26.5-25		

ENGINE : MODEL		C9.3	S/N	RYE00568
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			

OPERATION PUMP

Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

TRANSMISSION & TRAVEL

T/M TYPE	PS · DD	
Transmission	FAIR · Attn	
Travel	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only C only None

FRONT & CYLINDERS

Arm	FAIR · Attn	*1
Bell crank	FAIR · Attn	
Bucket	FAIR · Attn	
Articulate	FAIR · Attn	*2

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR (FAIR • WORN • UNEVEN WEAR)	

COMMENT

STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING

RIDE CONTROL	☒ YES	☐ NO
--------------	--------------------------------------	--------------------------

ATTACHMENTS

STD BKT	YES • OTHER		
BLADE	YES • NO	Piping for Tilt	YES • NO

COMMENT

*1 右シリンダーにじみあり RIGHT CYLINDER: OIL OOOZING
*2 左シリンダー油漏れ小、右シリンダー油漏れあり
*2 CYLINDERS: OIL LEAKING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) **4**

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。