

INSPECTION SHEET 検品書
ROLLER ローラー

INSPECTION DATE	2026/7/31	MAKE	BOMAG	MODEL	BW211D-4
SERIAL	101583091620		STAMP	101583091620	
HR METER	2706	HR	Odometer	-	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	20.5-25

ENGINE : MODEL TCD2013L04 S/N 11064676		UNDERCARRIAGE : See Photos. 写真参照	
Oil leakage	FAIR · Attn	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
Blow-By	FAIR · Attn	TIRE WEAR (FAIR · WORN · UNEVEN WEAR)	
Sound	FAIR · Attn	COMMENT	
Oil	FAIR · Attn	中折れ周りホースひび割れあり	
Exhaust Color	FAIR · Attn	SOME HOSE AROUND ARTICULATE PART: MUCH CRACKED	
US EPA	YES · NO	E/Gフード開閉ロックハンドル固着気味	
OPERATION PUMP		ENGINE HOOD LATCH KNOB: A LITTLE STUCK	
Sound	FAIR · Attn	リペイントあり REPAINTED	
Oil leakage	FAIR · Attn	*1 右窓開いたままで開閉ロック解除できない	
Power	FAIR · Attn	*1 RIGHT SIDE GLASS: UNABLE TO SHUT	
COOLING SYSTEM		(THE GLASS LOCK: UNABLE TO RELEASE TO SHUT THE GLASS)	
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	PS · DD		
Transmission	FAIR · Attn		
Travel	FAIR · Attn		
FOOT BRAKE	FAIR · Attn		
PARKING BRAKE	FAIR · Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn	破れあり CUT	
Glasses	FAIR · Attn	*1	
AirCon	A/C · H/C · H only · C only · None		
OTHERS			
Vibratory	FAIR · Attn		
Watering	FAIR · Attn		
Articulate	FAIR · Attn	RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。