

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/6	MAKE	HITACHI	MODEL	ZX225USRK-3
SERIAL	HCM1U600E00207949		STAMP	HCM1U600E00207949	
HR METER	13595	HR	YEAR	2008	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		4HK1	S/N
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · NO		
MAIN PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn	油漏れあり OIL LEAKING	
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
OPERATING SYSTEM			
Swing	FAIR · Attn		
Travel	FAIR · Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn	破れあり TORN	
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · None		
BOOM / ARM / BKT			
Boom	FAIR · Attn		
Boom Cylinder	FAIR · Attn	右側油漏れあり RIGHT CYLINDER: OIL LEAKING	
Arm	FAIR · Attn		
Arm Cylinder	FAIR · Attn		
ATTACHMENT	FAIR · Attn		
BKT Cylinder	FAIR · Attn	傷、にじみあり SCRATCHED, OIL OOZING	

UNDERCARRIAGE :				See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
COMMENT 					
BKT	STD (<u>SLOPE</u>) NARROW / SKELETON / OTHER()				
Lever	LONG ▪ (<u>WRIST</u>)				
Multi	(<u>MULTI</u>) ▪ 2 ▪ NO				
ARM-CRANE	YES ▪ (<u>NO</u>)				
BLADE	YES ▪ (<u>NO</u>)				
OFFSET	YES ▪ (<u>NO</u>)				
OFFSET Cylinder	FAIR ▪ Attn				
Piping	(<u>YES</u>) ▪ NO	Breaker only ▪ Multi			5
COMMENT 底板欠 SOME UNDER COVER: MISSING コントロールバルブにじみあり CONTROL VALVE: OIL OOZING バックカメラ不良 BACK MONITOR: MALFUNCTION A/Cベルト欠、コンプレッサ取付フレーム曲がりあり A/C: NO BELT, COMPRESSOR MOUNTING FRAME: DISTORTED 					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。