

INSPECTION SHEET 検品書
CARRY DUMP キャリーダンプ

INSPECTION DATE	2026/8/20	MAKE	YANMAR	MODEL	C12R-B		
SERIAL	28511			STAMP	28511		
HR METER	928	HR	Odometer	km	YEAR	2015	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	230R	TIRE	

ENGINE : MODEL		S/N		18463	
Oil leakage	FAIR · Attn				
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE			
Sound	FAIR · Attn				
Oil	FAIR · Attn				
Exhaust Color	FAIR · Attn				
US EPA	YES · NO				
OPERATION PUMP					
Sound	FAIR · Attn				
Oil leakage	FAIR · Attn				
Power	FAIR · Attn				
COOLING SYSTEM					
Radiator	FAIR · Attn				
Oil Cooler	FAIR · Attn				
TRANSMISSION & TRAVEL					
T/M TYPE	PS · DD		No. OF GEARS	1 GEARS	
Transmission	FAIR · Attn				
Travel	FAIR · Attn				
Swing	FAIR · Attn				
Articulate	FAIR · Attn				
FOOT BRAKE	FAIR · Attn				
PARKING BRAKE	FAIR · Attn				
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN · FAIR · DIRTY				
Operator's Seat	FAIR · Attn	破れ小 TINY CUT			
Glasses	FAIR · Attn				
AirCon	A/C · H/C · H only · C only · None				

MAIN FRAME					
MAIN FLAME		(FAIR)	▪ Attn		
VESSEL					
VESSEL		(FAIR)	(Attn)	補修跡あり REPAIRED	
REAR GATE TYPE		(NORMAL)		▪ L-GATE (FLAT)	
REAR GATE		(FAIR)	▪ Attn		
UNDERCARRIAGE:					
See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4
TIRE WEAR		FAIR ▪ WORN ▪ UNEVEN WEAR			
COMMENT 					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。