

INSPECTION SHEET 検品書
ROLLER ローラー

INSPECTION DATE	2026/8/18	MAKE	CAT	MODEL	CS11GC-01A
SERIAL	CAT0CS11ERFL00362			STAMP	CAT0CS11ERFL00362
HR METER	2803	HR	Odometer	—	km
YEAR	2015		YR		
CAB/CNP	☒ ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	23.1-26

ENGINE : MODEL C3.6 S/N J3649935	UNDERCARRIAGE : See Photos. 写真参照	
Oil leakage ☒ FAIR · Attn	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4	
Blow-By ☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE	TIRE WEAR ☒ FAIR · WORN · UNEVEN WEAR	
Sound ☒ FAIR · Attn	COMMENT 	
Oil ☒ FAIR · Attn		
Exhaust Color ☒ FAIR · Attn		
US EPA ☒ YES · NO		
OPERATION PUMP		
Sound ☒ FAIR · Attn		
Oil leakage ☒ FAIR · Attn		
Power ☒ FAIR · Attn		
COOLING SYSTEM		
Radiator ☒ FAIR · Attn		
Oil Cooler ☒ FAIR · Attn		
TRANSMISSION & TRAVEL		
T/M TYPE ☒ PS · DD		
Transmission ☒ FAIR · Attn		
Travel ☒ FAIR · Attn		
FOOT BRAKE ☒ FAIR · Attn		
PARKING BRAKE ☒ FAIR · Attn		
INTERIOR See Photos. 写真参照		
INTERIOR COND. ☒ CLEAN · FAIR · DIRTY		
Operator's Seat ☒ FAIR · Attn		
Glasses ☒ FAIR · Attn		
AirCon ☒ A/C · H/C · H only · C only · None		
OTHERS		
Vibratory ☒ FAIR · Attn		
Watering ☒ FAIR · Attn		
Articulate ☒ FAIR · Attn		
		RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。