INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2026/8/5	CATEGORY	0.7m3用小割 SECONDARY CRUSHER for 0.7m3				
MAKE	NPK			MODEL	G-18		
SERIAL	NO PLATE			STAMP	30761		
HR METER	- HR	Odometer	km	YEAR	YR		
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	SHOE		TIRE			

ENGINE	MODEL		S/N		
Oil leakage	FAIR ・ Attn		Oil	FAIR ・ Attn	
Blow-By	FAIR ・ Attn	A LITTLE ・MIDDLE ・SEVERE	Exhaust Color	FAIR ・ Attn	
Sound	FAIR ・ Attn		EPA	YES ・ NO	

CONDITION	FAIR ・ Attn	

未確認 OPERATION: NOT CHECKED

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	TIRE WEAR	FAIR ・WORN・ UNEVEN WEAR

COMMENT

シリンダー油漏れあり CYLINDER: OIL LEAKING

80φ ×310mm

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。