

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/8/6	MAKE	KOMATSU	MODEL	WA380-7
SERIAL	10975		STAMP	WA118-10975	
HR METER	14041	HR	Odometer	63705	km
				YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	23.5-25 16PR

ENGINE : MODEL		6D107E-2	S/N	26648293
Oil leakage	FAIR	Attn	E/G周りにじみあり AROUND ENGINE: OIL OOZING	
Blow-By	FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		

OPERATION PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn

COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn

TRANSMISSION & TRAVEL		
T/M TYPE	PS · DD	
Transmission	FAIR · Attn	
Travel	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN	FAIR
Operator's Seat	FAIR	シートカバーあり W/SEAT COVER
Glasses	FAIR	
AirCon	A/C	H/C H only C only None

FRONT & CYLINDERS		
Arm	FAIR · Attn	
Bell crank	FAIR · Attn	
Bucket	FAIR · Attn	
Articulate	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR • WORN • UNEVEN WEAR

COMMENT	
Fタイヤのみスノータイヤ FRONT TIRES: SNOW	
左Rタイヤ1本インナーバーストあり(危険)	
REAR LEFT TIRE: INNER BURST (DANGER)	
STEERING TYPE	WHEEL STEERING / COMMAND STEERING / LEVER STEERING

RIDE CONTROL	☒ YES • ☐ NO
--------------	---

ATTACHMENTS			
STD BKT	☒ YES	☐ OTHER	
BLADE	☒ YES	☐ NO	Piping for Tilt ☒ YES ☐ NO

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。