

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |         |                   |         |
|-----------------|----------------------------------------|------|---------|-------------------|---------|
| INSPECTION DATE | 2026/8/5                               | MAKE | KOMATSU | MODEL             | PC120-8 |
| SERIAL          | 80955                                  |      | STAMP   | KMTPC202K02080955 |         |
| HR METER        | 4973                                   | HR   | YEAR    | YR                |         |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE    | 500G              |         |

|                           |       |          |                            |        |
|---------------------------|-------|----------|----------------------------|--------|
| ENGINE : MODEL            |       | 4D95LE-5 | S/N                        | 506311 |
| Oil leakage               | FAIR  | Attn     |                            |        |
| Blow-By                   | FAIR  | Attn     | A LITTLE · MIDDLE · SEVERE |        |
| Sound                     | FAIR  | Attn     |                            |        |
| Oil                       | FAIR  | Attn     |                            |        |
| Exhaust Color             | FAIR  | Attn     |                            |        |
| US EPA                    | YES   | NO       |                            |        |
| MAIN PUMP                 |       |          |                            |        |
| Sound                     | FAIR  | Attn     |                            |        |
| Oil leakage               | FAIR  | Attn     |                            |        |
| Power                     | FAIR  | Attn     |                            |        |
| COOLING SYSTEM            |       |          |                            |        |
| Radiator                  | FAIR  | Attn     |                            |        |
| Oil Cooler                | FAIR  | Attn     |                            |        |
| OPERATING SYSTEM          |       |          |                            |        |
| Swing                     | FAIR  | Attn     |                            |        |
| Travel                    | FAIR  | Attn     |                            |        |
| INTERIOR See Photos. 写真参照 |       |          |                            |        |
| INTERIOR COND.            | CLEAN | FAIR     | DIRTY                      |        |
| Operator's Seat           | FAIR  | Attn     | 破れあり TORN                  |        |
| Glasses                   | FAIR  | Attn     |                            |        |
| AirCon                    | A/C   | H/C      | H only                     | C only |
| None                      |       |          |                            |        |
| BOOM / ARM / BKT          |       |          |                            |        |
| Boom                      | FAIR  | Attn     | ガタあり LOOSE                 |        |
| Boom Cylinder             | FAIR  | Attn     |                            |        |
| Arm                       | FAIR  | Attn     | ガタあり LOOSE                 |        |
| Arm Cylinder              | FAIR  | Attn     |                            |        |
| ATTACHMENT                | FAIR  | Attn     |                            |        |
| BKT Cylinder              | FAIR  | Attn     |                            |        |

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。