

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/8/7	MAKE	CAT	MODEL	D6R
SERIAL	CAT00D6RPBPZ00113			STAMP	CAT00D6RPBPZ00113
HR METER	10974	HR	SHOE	1000LGP	YEAR YR
BLADE	STRAIGHT ☒ ST/TILT ☐ PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB ☒ CAB ☐ ROPS CNP / CNP / NONE

ENGINE : MODEL		S/N	UNDERCARRIAGE See Photos. 写真参照	
Oil leakage	☒ FAIR · Attn		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4	
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE	COMMENT	
Sound	☒ FAIR · Attn			
Oil	☒ FAIR · Attn			
Exhaust Color	☒ FAIR · Attn			
US EPA	YES · ☒ NO			
OPERATION PUMP			Ripper	MULTI · S/S Shanks PCS
Sound	☒ FAIR · Attn		Ripper CYLD.	FAIR · Attn
Oil leakage	☒ FAIR · Attn		COMMENT	
Power	☒ FAIR · Attn		A/C風出ない A/C: NOT BLOWING AIR	
COOLING SYSTEM				
Radiator	☒ FAIR · Attn			
Oil Cooler	☒ FAIR · Attn			
TRANSMISSION & TRAVEL				
T/M TYPE	☒ PS · DD	DIFF. STEERING ☒ YES · NO		
Transmission	☒ FAIR · Attn			
Travel	☒ FAIR · Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY			
Operator's Seat	☒ FAIR · Attn	破れあり CUTS		
Glasses	☒ FAIR · Attn			
AirCon	☒ A/C · H/C · H only · C only · None			
BLADE & CYLINDERS				
BLADE	☒ FAIR · Attn			
CYLD.(R)	☒ FAIR · Attn			
CYLD.(L)	☒ FAIR · Attn			
TILT CYLD	☒ FAIR · Attn			
ANGLE CYLD	FAIR · Attn		RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。