

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/20	MAKE	CAT	MODEL	312C
SERIAL	CAT0312CPCAE01908		STAMP	CAT0312CPCAE01908	
HR METER	7825	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL		S/N
Oil leakage	FAIR	Attn
Blow-By	FAIR	Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn
Oil	FAIR	Attn
Exhaust Color	FAIR	Attn
US EPA	YES	NO
MAIN PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn
COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn
OPERATING SYSTEM		
Swing	FAIR	Attn
Travel	FAIR	Attn
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR	Attn 破れ大 TORN
Glasses	FAIR	Attn
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR	Attn
Boom Cylinder	FAIR	Attn 左右油漏れ小 CYLINDERS: OIL LEAKING
Arm	FAIR	Attn
Arm Cylinder	FAIR	Attn
ATTACHMENT	FAIR	Attn
BKT Cylinder	FAIR	Attn にじみあり OIL OOZING

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2
COMMENT		
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()	
Lever	LONG · WRIST	
Multi	MULTI · 2 · NO	
ARM-CRANE	YES · NO	
BLADE	YES · NO	
OFFSET	YES · NO	
OFFSET Cylinder	FAIR · Attn	
Piping	YES · NO Breaker only · Multi	
COMMENT		
左サイドラジエータカバーキャッチ不良(バールでこねると開く)		
FRONT LEFT SIDE COVER LATCH: MALFUNCTION		
(ABLE TO PRY OPEN WITH A PRY BAR)		
マフラータイコの先の煙突部溶接外れあり		
WELDED PART OF EXHAUST PIPE: COME OFF		
A/C効かない A/C: MALFUNCTION		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。