

INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2026/8/18	CATEGORY	自走式破砕機 MOBILE CRUSHER		
MAKE	KOMATSU		MODEL	BR380JG-1E0	
SERIAL	2820		STAMP	NOT FOUND	
HR METER	6627	HR	Odometer	km	YEAR 2015 YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / <u>NONE</u>		SHOE	500G	TIRE

ENGINE	MODEL 6D107E-1	S/N	26638656		
Oil leakage	<u>FAIR</u> ・ Attn	Oil	<u>FAIR</u> ・ Attn		
Blow-By	<u>FAIR</u> ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE	Exhaust Color	<u>FAIR</u> ・ Attn	
Sound	<u>FAIR</u> ・ Attn	EPA	YES ・ <u>NO</u>		

CONDITION	<u>FAIR</u> ・ Attn	
走行: HI/LOW切替不良 HI/LO TRAVEL SWITCH: MALFUNCTION		

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR ・ WORN ・ UNEVEN WEAR
COMMENT			
一部リペイントあり PARTLY REPAINTED			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4		

This inspection information is for reference only at “the inspection date” by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。