

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/18	MAKE	KOMATSU	MODEL	PC30MR-5
SERIAL	53899		STAMP	KMTPC262EJE053899	
HR METER	3656	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	300G	

ENGINE : MODEL		S/N
Oil leakage	FAIR Attn	
Blow-By	FAIR Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR Attn	
Oil	FAIR Attn	
Exhaust Color	FAIR Attn	
US EPA	YES NO	
MAIN PUMP		
Sound	FAIR Attn	
Oil leakage	FAIR Attn	
Power	FAIR Attn	
COOLING SYSTEM		
Radiator	FAIR Attn	
Oil Cooler	FAIR Attn	
OPERATING SYSTEM		
Swing	FAIR Attn	ガタあり SWING: LOOSE
Travel	FAIR Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR Attn	
Glasses	FAIR Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR Attn	
Boom Cylinder	FAIR Attn	
Arm	FAIR Attn	
Arm Cylinder	FAIR Attn	
ATTACHMENT	FAIR Attn	
BKT Cylinder	FAIR Attn	

UNDERCARRIAGE :		See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
BKT	STD /SLOPE / NARROW / SKELETON / OTHER()	
Lever	LONG · WRIST	
Multi	MULTI · 2 · NO	
ARM-CRANE	YES · NO	
BLADE	YES · NO	
OFFSET	YES · NO	
OFFSET Cylinder	FAIR · Attn	
Piping	YES · NO Breaker only · Multi	
COMMENT		
スイングガタあり SWING PART: LOOSE		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。