

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/8/6	MAKE	TADANO	MODEL	GR-250N-2
SERIAL No.	PLATE : FB5779		STAMP : T003-0534		
HR METER	33067	HR	Odometer	129461	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	*1
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
OPERATION PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Computer	OK · NG	
Swing	FAIR · Attn	
Travel	FAIR · Attn	
TRANSMISSION		
Transmission	FAIR · Attn	
No. OF GEARS	4 GEAR	
4WD	4WD · 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	破れ、穴あり CUTS, HOLE
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
COMMENT		

BOOM				
No. of Section	4		SECTIONS	
CRACK/ENFORCEMENT	FAIR	▪	Attn	
DERRICKING CYL.	FAIR	▪	Attn	
EXTENSION CYL.	FAIR	▪	Attn	
JIB	YES	▪	NO	
JIB TYPE	STD	▪	PWR	
MAIN & SUB WIRE	YES	▪	NO	
FREE FALL	YES	▪	NO	
HOOK	25t, BALL			
UNDERCARRIAGE : See Photos. 写真参照				
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				3
TIRE WEAR	FAIR ▪ WORN ▪ UNEVEN WEAR			
COMMENT				
テールランプカバーフレームヘコミあり				
RIGHT TAIL LAMP FRAME: A LITTLE DEFORMED				
OUTRIGGERS				
OUTRIGGERS	X	▪	H	
OUTRIGGERS COND.	FAIR	▪	Attn	
Oil leakage (JACK CYL.)	FRONT	L	▪ R	REAR L ▪ R
Oil leakage (SLIDE CYL.)	FRONT	L	▪ R	REAR L ▪ R
COMMENT				
*1 E/Gヘッド油漏れあり CYLINDER HEAD: OIL LEAKING				
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。