

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/8/24	MAKE	KCM	MODEL	90ZV-2
SERIAL	90C5-0507			STAMP	90C5-0507
HR METER	13412 / 13357	HR	Odometer	39765Miles / 63346	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	26.5R25
YEAR	2012			YR	

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR • Attn	
Blow-By	☒ FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	☒ FAIR • Attn	
Oil	☒ FAIR • Attn	
Exhaust Color	☒ FAIR • Attn	
US EPA	YES • ☒ NO	
OPERATION PUMP		
Sound	☒ FAIR • Attn	
Oil leakage	☒ FAIR • Attn	
Power	☒ FAIR • Attn	
COOLING SYSTEM		
Radiator	☒ FAIR • Attn	
Oil Cooler	☒ FAIR • Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	☒ PS • DD	
Transmission	☒ FAIR • Attn	
Travel	☒ FAIR • Attn	
FOOT BRAKE	☒ FAIR • Attn	
PARKING BRAKE	☒ FAIR • Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • ☒ FAIR • DIRTY	
Operator's Seat	☒ FAIR • Attn	
Glasses	☒ FAIR • Attn	
AirCon	☒ A/C • H/C • H only • C only • None	
FRONT & CYLINDERS		
Arm	☒ FAIR • Attn	
Bell crank	☒ FAIR • Attn	
Bucket	☒ FAIR • Attn	
Articulate	☒ FAIR • Attn	ガタあり LOOSE

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR • ☒ WORN • UNEVEN WEAR
COMMENT	
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING	
RIDE CONTROL	☒ YES • NO
ATTACHMENTS	
STD BKT	☒ YES • OTHER
BLADE	YES • ☒ NO Piping for Tilt YES • ☒ NO
COMMENT	
リペイントあり REPAINTED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。