

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/18	MAKE	CAT	MODEL	315FLCR
SERIAL	CAT0315FCTDY14479		STAMP	CAT0315FCTDY14479	
HR METER	4099 / 4109 HR		YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE :	MODEL	C4.4	S/N	W7N81539
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			
MAIN PUMP				
Sound	FAIR · Attn			
Oil leakage	FAIR · Attn			
Power	FAIR · Attn			
COOLING SYSTEM				
Radiator	FAIR · Attn			
Oil Cooler	FAIR · Attn			
OPERATING SYSTEM				
Swing	FAIR · Attn			
Travel	FAIR · Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · FAIR · DIRTY			
Operator's Seat	FAIR · Attn			
Glasses	FAIR · Attn			
AirCon	A/C · H/C · H only · C only · None			
BOOM / ARM / BKT				
Boom	FAIR · Attn			
Boom Cylinder	FAIR · Attn			
Arm	FAIR · Attn			
Arm Cylinder	FAIR · Attn			
ATTACHMENT	FAIR · Attn	ガタあり LOOSE		
BKT Cylinder	FAIR · Attn			

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT シューパッド:カスが付いているだけ RUBBER PADS: ALMOST GONE		
BKT	STD / SLOPE / NARROW / SKELETON / OTHER()	
Lever	LONG ▪ WRIST	
Multi	MULTI ▪ 2 ▪ NO	
ARM-CRANE	YES ▪ NO	
BLADE	YES ▪ NO	
OFFSET	YES ▪ NO	
OFFSET Cylinder	FAIR ▪ Attn	
Piping	YES ▪ NO	Breaker only ▪ Multi
COMMENT ボディリペイントあり BODY: REPAINTED		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。