

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/24	MAKE	KOMATSU	MODEL	PC228UU-1
SERIAL	10571		STAMP	PC228-010571 HARD TO READ	
HR METER	7833	HR	YEAR	2001	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL S/N Oil leakage FAIR · Attn Blow-By FAIR · Attn A LITTLE · MIDDLE · SEVERE Sound FAIR · Attn Oil FAIR · Attn Exhaust Color FAIR · Attn US EPA YES · NO MAIN PUMP Sound FAIR · Attn Oil leakage FAIR · Attn Power FAIR · Attn COOLING SYSTEM Radiator FAIR · Attn Oil Cooler FAIR · Attn OPERATING SYSTEM Swing FAIR · Attn Travel FAIR · Attn INTERIOR See Photos. 写真参照 INTERIOR COND. CLEAN · FAIR · DIRTY Operator's Seat FAIR · Attn Glasses FAIR · Attn 天窓ひび割れあり SKYLIGHT: MUCH CRACKED AirCon A/C · H/C · H only · C only · None BOOM / ARM / BKT Boom FAIR · Attn Boom Cylinder FAIR · Attn Arm FAIR · Attn ガタあり LOOSE Arm Cylinder FAIR · Attn ATTACHMENT FAIR · Attn BKT Cylinder FAIR · Attn 傷、ヘコミあり SCRATCHED, DENT	UNDERCARRIAGE : See Photos. 写真参照 RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3 COMMENT BKT STD / SLOPE / NARROW / SKELETON / OTHER () Lever LONG · WRIST Multi MULTI · 2 · NO ARM-CRANE YES · NO *1 BLADE YES · NO OFFSET YES · NO ガタあり LOOSE OFFSET Cylinder FAIR · Attn Piping YES · NO Breaker only · Multi COMMENT リペイントあり REPAINTED *1 ユニット電源入らない CRANE UNIT: UNABLE TO TURN ON RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3
--	--

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。