

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2026/7/25	MAKE	HITACHI	MODEL	CX900HD
SERIAL No.	PLATE :	25FP000153	STAMP	25FP000153	
HR METER	36152	HR	SHOE	850FLAT	YEAR YR

ENGINE : MODEL		S/N
Oil leakage	FAIR ☒ Attn	*1
Blow-By	FAIR ☒ Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR ☒ Attn	
Oil	FAIR ☒ Attn	
Exhaust Color	FAIR ☒ Attn	
OPERATION PUMP		
Sound	FAIR ☒ Attn	
Oil leakage	FAIR ☒ Attn	
Power	FAIR ☒ Attn	
COOLING SYSTEM		
Radiator	FAIR ☒ Attn	
Oil Cooler	FAIR ☒ Attn	
OPERATING SYSTEM		
Computer	OK ☒ NG	未確認 NOT CHECKED
Swing	FAIR ☒ Attn	
Travel	FAIR ☒ Attn	
BOOM		
MAIN BOOM	TOP, BOTTOM, 9m × 2, 6m × 1, 3m × 1	
BOOM TOTAL	40m	
TOP SHEAVE	YES ☒ NO	
JIB		
TOWER		

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN ☒ FAIR · DIRTY	
Operator's Seat	FAIR ☒ Attn	
Glasses	FAIR ☒ Attn	
AirCon	A/C ☒ H/C · H only · C only · None	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
第3ドラム付 W/3rd DRUM		
3mブームヘコミあり 3m BOOM: DENT		
WEIGHT	4	
HOOK	90t, 50t, 45t, LIGHT HOOK × 2	
FREE FALL	YES ☒ NO	
LIFTER	YES ☒ NO	
COMMENT		
主・補巻ワイヤーカシメ加工あり		
MAIN HOIST WIRE & AUXILIARY HOIST WIRE: SWAGING		
ワイヤーフケット欠 WIRE SOCKETS: MISSING		
右ガントリーシリンダー油漏れあり RIGHT GANTRY CYLINDER: OIL LEAKING		
90t, 50t, 45t, 軽量フック × 1、馬一式別置きあり		
90t, 50t, 45t, LIGHT HOOK × 1, & A SET OF JACK STANDS: NOT ATTACHED		
*1 E/G後ろにじみあり REAR PART OF ENGINE: OIL OOZING		
@NARITA YARD BOOM: TOP, BOTTOM, 6m × 1, 3m × 1		
@SAKURA YARD		
BOOM: 9m × 2, TOOL BOX × 1, A SET OF JACK STANDS, LADDER × 1		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。