

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/17	MAKE	CAT	MODEL	320E-2
SERIAL	CAT0320EPSXE01087			STAMP	CAT0320EPSXE01087
HR METER	7762 / 7802		HR	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	790G

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	破れあり HUGE CUTS
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
ATTACHMENT	FAIR · Attn	ガタあり LOOSE
BKT Cylinder	FAIR · Attn	傷あり SCRATCHED

UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
COMMENT					
右トラックローラーガタあり SOME RIGHT TRACK ROLLERS: LOOSE					
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER ()				
Lever	LONG ▪ (WRIST)				
Multi	(MULTI) ▪ 2 ▪ NO				
ARM-CRANE	(YES) ▪ NO				
BLADE	YES ▪ (NO)				
OFFSET	YES ▪ (NO)				
OFFSET Cylinder	FAIR ▪ Attn				
Piping	YES ▪ (NO)	Breaker only ▪ Multi			
COMMENT					
ブーム背面ホースひび割れあり					
SOME HOSE AROUND BOOM: MUCH CRACKED					
バックカメラ不良(後付けあり)					
BACK MONITOR: MALFUNCTION (W/RETROFITTED BACK MONITOR)					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。