

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/17	MAKE	KATO	MODEL	HD512-6
SERIAL	KWJ22E01CG0005413			STAMP	5413
HR METER	6427	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	500G

ENGINE : MODEL		4JJ1	S/N	189420
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only · None
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn		
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn	ガタ、補修跡あり LOOSE, REPAIRED	
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE :						See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)								4			
COMMENT											
全体的にトラックフレームリペイントあり TRACK FRAME: REPAINTED											
BKT		(STD / SLOPE / NARROW / SKELETON / OTHER())									
Lever		LONG		▪		(WRIST)					
Multi		MULTI		▪		2		▪		NO	
ARM-CRANE		(YES)		▪		NO					
BLADE		YES		▪		(NO)					
OFFSET		YES		▪		(NO)					
OFFSET Cylinder		FAIR		▪		Attn					
Piping		YES		▪		(NO)		Breaker only ▪ Multi			
COMMENT											
I・Hリンクガタ大 I-LINKS & H-LINK: MUCH LOOSE											
縦ガタあり(ブーム等を上げるとCABが縦にガタガタ揺れる)											
BODY: VERTICAL SHAKING WHEN OPERATING WORKING EQUIPMENT PART											
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)									4		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。