

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/8/21	MAKE	TADANO	MODEL	GR-160N-1
SERIAL No.	PLATE : 525935		STAMP : T002-0128		
HR METER	11487	HR	Odometer	100659	km
TIRE SIZE	325/95R24		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR • Attn	
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn	
Oil	FAIR • Attn	
Exhaust Color	FAIR (Attn)	白煙あり WHITE FUMES

OPERATION PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Computer	OK	NG	
Swing	FAIR	Attn	
Travel	FAIR	Attn	

TRANSMISSION

Transmission	FAIR	Attn	
No. OF GEARS	4	GEARS	
4WD	4WD	6WD	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN • FAIR • DIRTY					
Operator's Seat	FAIR	Attn				
Glasses	FAIR	Attn				
AirCon	A/C		H/C	H only	C only	None

COMMENT

BOOM

No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	FAIR	▪ Attn	
DERRICKING CYL.	FAIR	▪ Attn	
EXTENSION CYL.	FAIR	▪ Attn	
JIB	YES	▪ NO	
JIB TYPE	STD	▪ PWR	
MAIN & SUB WIRE	YES	▪ NO	
FREE FALL	YES	▪ NO	
HOOK	16t, BALL		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
TIRE WEAR	FAIR • WORN • UNEVEN WEAR	

COMMENT

OUTRIGGERS

OUTRIGGERS	☒ X	▪	H			
OUTRIGGERS COND.	☒ FAIR	▪	Attn			
Oil leakage (JACK CYL.)	FRONT	L	▪	R	REAR	L ▪ R
Oil leakage (SLIDE CYL.)	FRONT	L	▪	R	REAR	L ▪ R

COMMENT

エアー溜まりずらい(自走不可) AIR: HARD TO STORE (UNABLE TO RUN ON PUBLIC ROADS)		3
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。