

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/8/25	MAKE	TADANO	MODEL	GR-600N-1
SERIAL No.	PLATE : FD5255		STAMP : TR600-0255		
HR METER	5736	HR	Odometer	75021	km
TIRE SIZE	505/95R25		YEAR	2006	YR

ENGINE : MODEL		S/N	
Oil leakage	FAIR • Attn		
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE	
Sound	FAIR • Attn		
Oil	FAIR • Attn		
Exhaust Color	FAIR • Attn		
OPERATION PUMP			
Sound	FAIR • Attn		
Oil leakage	FAIR • Attn		
Power	FAIR • Attn		
COOLING SYSTEM			
Radiator	FAIR • Attn		
Oil Cooler	FAIR • Attn		
OPERATING SYSTEM			
Computer	OK • NG		
Swing	FAIR • Attn		
Travel	FAIR • Attn		
TRANSMISSION			
Transmission	FAIR • Attn		
No. OF GEARS	4	GEARS	
4WD	4WD • 6WD		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN • FAIR • DIRTY		
Operator's Seat	FAIR • Attn	破れあり CUTS	
Glasses	FAIR • Attn		
AirCon	A/C • H/C • H only • C only • None		
COMMENT			

BOOM					
No. of Section	6		SECTIONS		
CRACK/ENFORCEMENT	☒ FAIR	▪ Attn			
DERRICKING CYL.	☒ FAIR	▪ Attn			
EXTENSION CYL.	☒ FAIR	▪ Attn			
JIB	☒ YES	▪ NO			
JIB TYPE	STD	▪ ☒ PWR			
MAIN & SUB WIRE	☒ YES	▪ NO			
FREE FALL	YES	▪ ☒ NO			
HOOK	60t, 25t, BALL				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					2
TIRE WEAR	☒ FAIR ▪ ☐ WORN ▪ ☐ UNEVEN WEAR				
COMMENT					
右Fタイヤ亀裂あり FRONT RIGHT TIRE SIDEWALL: CUTS					
OUTRIGGERS					
OUTRIGGERS	X	▪ ☒ H			
OUTRIGGERS COND.	☒ FAIR	▪ Attn			
Oil leakage (JACK CYL.)	FRONT	L ▪ R	REAR	L ▪ R	
Oil leakage (SLIDE CYL.)	FRONT	L ▪ R	REAR	L ▪ R	
COMMENT					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。