

INSPECTION SHEET 検品書
CARRY DUMP キャリーダンプ

INSPECTION DATE	2026/8/24	MAKE	MOROOKA	MODEL	MST-1500VDLG		
SERIAL	051039			STAMP	051039		
HR METER	6462	HR	Odometer	km	YEAR	2020	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	700R	TIRE	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
OPERATION PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS · DD	No. OF GEARS 2 GEARS
Transmission	FAIR · Attn	
Travel	FAIR · Attn	
Swing	FAIR · Attn	
Articulate	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	

MAIN FRAME		
MAIN FLAME	FAIR · Attn	
VESSEL		
VESSEL	FAIR · Attn	
REAR GATE TYPE	NORMAL · L-GATE (FLAT)	
REAR GATE	FAIR · Attn	
UNDERCARRIAGE: See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
TIRE WEAR	FAIR · WORN · UNEVEN WEAR	
COMMENT		
リペイントあり REPAINTED		
フォワードダ仕様 FORWARDER SPECIFICATIONS		
グラップルホースにじみあり GRAPPLE HOSE: OIL OOZING		
クーラー冷えない COOLER: MALFUNCTION		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。