

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2026/8/17	MAKE	NIPPON SHARYO	MODEL	DH350Ⅲ
SERIAL No.	PLATE :	A30801	STAMP	A30801	
HR METER	2918	HR	SHOE	760FLAT	YEAR 1986 YR

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	
OPERATION PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	
COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	
OPERATING SYSTEM		
Computer	☒ OK · NG	未確認 NOT CHECKED
Swing	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	
BOOM		
MAIN BOOM	TOP, BOTTOM, 6m × 1, 3m × 2	
BOOM TOTAL	22m	
TOP SHEAVE	YES · ☒ NO	
JIB		
TOWER		

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY	
Operator's Seat	☒ FAIR · Attn	破れ大 HUGE CUT
Glasses	☒ FAIR · Attn	
AirCon	A/C · H/C · H only · C only · ☒ None	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2
COMMENT		
左右キャタ緩みあり TRACK LINKS: WORN		
WEIGHT	2	
HOOK	35t, LIGHT HOOK	
FREE FALL	☒ YES · NO	
LIFTER	YES · ☒ NO	
COMMENT		
下部ブーム下パイプヘコミあり		
SOME LOWER LATTICE PIPES OF BOOM BOOM: BENT		
ブームジョイントピン2本、ペンダントジョイントピン9本: CAB内にあり		
2 BOOM JOINT PINS & 9 PENDANT JOINT PINS: PUTTING IN CAB		
ブームジョイントピン2本欠 2 BOOM JOINT PINS: MISSING		
@NARITA YARD		
BOOM: TOP, BOTTOM		
PENDANT: 6m × 2, 3m × 4		
@SAKURA YARD		
BOOM: 6m × 1, 3m × 2		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。