

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2026/8/17	MAKE	KOBELCO	MODEL	7200
SERIAL No.	PLATE :	JE02-00058	STAMP	JE02-00058	
HR METER	20646	HR	SHOE	1070FLAT	YEAR YR

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	
OPERATION PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	
COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	
OPERATING SYSTEM		
Computer	☒ OK · NG	*1
Swing	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	
BOOM		
MAIN BOOM	TOP, BOTTOM, 9m × 5, 6m × 3, 3m × 3, TAPER 5.4m × 1	
BOOM TOTAL	88.4m	
*2		
TOP SHEAVE	☒ YES · NO	
JIB		
TOWER	58m + 48m	
TOP, BOTTOM, 9m × 2, 6m × 1, 3m × 2		

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY	
Operator's Seat	☒ FAIR · Attn	破れ大 CUTS
Glasses	☒ FAIR · Attn	
AirCon	☒ A/C · H/C · H only · C only · None	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
ブームサビあり BOOMS: RUSTY		
CAB: 新品 CAB: BRAND NEW		
WEIGHT	8, LOWER WEIGHT × 2	
HOOK	200t, 150t, 100t, 65t, 35t, BALL	
FREE FALL	YES · ☒ NO	
LIFTER	☒ YES · NO	
COMMENT		
*1 未確認、E51エラー表示あり NOT CHECKED, "E51" ERROR DISPLAY		
*2 9m × 1, 6m × 1, 3m × 2はタワークレーン用補助ジブと兼用		
*2 AUXILIARY JIB FOR TOWER CRANE (DUAL-PURPOSE FOR CRAWLER CRANE):		
9m × 1, 6m × 1, 3m × 2		
@NARITA YARD BOOM: TOP, BOTTOM, 9m × 1		
@FUNABASHI YARD		
BOOM: 9m × 3, 6m × 2, 3m × 1, TAPER 5.4m × 1, HOOK: 200t, 150t (W/HANGERS), 100t, 35t, BALL		
TOWER: TOP, BOTTOM, 9m × 2, 6m × 1, 3m × 2		
MAST, TOWER HEAD, GUIDE ROLLER, TOWER SPREADER, A SET OF PENDANTS,		
A SET OF CATCHERS, SOME PARTS, A SET OF STEPS		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。