

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/7	MAKE	KOMATSU	MODEL	PC228US-3E0
SERIAL	40761		STAMP	KMTPC161V02040761	
HR METER	6786	HR	YEAR	2007	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		6D107E-1	S/N	26509655
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn	*1	
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn	若干ゴリゴリ感あり A LITTLE RATTLING	
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn	破れあり TORN	
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only
				None
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn	左側にじみあり LEFT CYLINDER: OIL OOZING	
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn	ガタあり LOOSE	
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
COMMENT 					
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER())				
Lever	LONG ▪	(WRIST)			
Multi	MULTI ▪ 2 ▪	(NO)			
ARM-CRANE	(YES) ▪ NO				
BLADE	YES ▪	(NO)			
OFFSET	YES ▪	(NO)			
OFFSET Cylinder	FAIR ▪ Attn				
Piping	YES ▪	(NO)	Breaker only ▪ Multi		
COMMENT A/Cコンデンサー変形あり A/C CONDENSER: DISTORTED エアクリーナー腐食、警告灯点灯あり AIR CLEANER: CORRODED, WARNING LAMP FOR AIR CLEANER: ON *1 サブタンク割れ、水量警告灯点灯あり *1 SUB TANK: PARTLY BROKEN, WARNING LAMP FOR COOLANT LEVEL: ON 					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。