

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/8/19	MAKE	TCM	MODEL	870-2			
SERIAL	67000856			STAMP	S08-00856			
HR METER	1126	HR	Odometer	—	km	YEAR	1996	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	23.5-25			

ENGINE : MODEL		S/N
Oil leakage	FAIR	Attn
Blow-By	FAIR	Attn A LITTLE • MIDDLE • SEVERE
Sound	FAIR	Attn
Oil	FAIR	Attn
Exhaust Color	FAIR	Attn
US EPA	YES	NO
OPERATION PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn
COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn
TRANSMISSION & TRAVEL		
T/M TYPE	PS	DD
Transmission	FAIR	Attn
Travel	FAIR	Attn
FOOT BRAKE	FAIR	Attn
PARKING BRAKE	FAIR	Attn効かない MALFUNCTION
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • FAIR •	DIRTY
Operator's Seat	FAIR	Attn破れあり TORN
Glasses	FAIR	AttnF割れあり WINDSHIELD: CRACKED
AirCon	A/C • H/C • H only • C only • None	
FRONT & CYLINDERS		
Arm	FAIR	Attn
Bell crank	FAIR	Attn
Bucket	FAIR	Attn穴あり HOLE
Articulate	FAIR	Attn*1

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR	FAIR • WORN • UNEVEN WEAR
COMMENT	
ミッション下油漏れあり BOTTOM OF TRANSMISSION: OIL LEAKING	
タイヤひび割れあり SOME TIRE: MUCH CRACKED	
STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	YES • NO
ATTACHMENTS	
STD BKT	YES • OTHER
BLADE	YES • NO Piping for Tilt YES • NO
COMMENT	
燃料メーター不良 FUEL GAUGE: MALFUNCTION	
ホース全体的にひび割れあり SOME HOSES: A LITTLE DAMAGED	
*1 右シリンダーにじみ、ガタあり RIGHT CYLINDER: OIL OOZING, LOOSE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。