

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/8/21	MAKE	TADANO	MODEL	GR-120N-1
SERIAL No.	PLATE : FD1576		STAMP : TR120-1545		
HR METER	9464	HR	Odometer	116691	km
TIRE SIZE	275/80R22.5		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR Attn	*1
Blow-By	FAIR Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	FAIR ・ Attn	
Oil	FAIR ・ Attn	
Exhaust Color	FAIR Attn	白煙あり WHITE FUMES

OPERATION PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Computer	OK	NG
Swing	FAIR	Attn
Travel	FAIR	Attn

TRANSMISSION

Transmission	FAIR • Attn	
No. OF GEARS	3	GEARS
4WD	4WD • 6WD	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attrn	破れ、穴あり CUT, HOLE
Glasses	FAIR	Attrn	
AirCon	A/C	H/C	H only C only None

COMMENT

BOOM

No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	FAIR	▪ Attn	
DERRICKING CYL.	FAIR	▪ Attn	
EXTENSION CYL.	FAIR	▪ Attn	
JIB	YES	▪ NO	
JIB TYPE	STD	▪ PWR	
MAIN & SUB WIRE	YES	▪ NO	
FREE FALL	YES	▪ NO	
HOOK	12t, BALL		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		1
TIRE WEAR	FAIR • WORN • UNEVEN WEAR	

COMMENT

[illegible]

OUTRIGGERS

OUTRIGGERS	☒ H			
OUTRIGGERS COND.	☒ Attn			
Oil leakage (JACK CYL.)	FRONT	L • R	REAR	L • R
Oil leakage (SLIDE CYL.)	FRONT	L • R	REAR	L • R

COMMENT

*1 オイルパン下にじみあり LOWER PART OF OIL PAN: OIL OOZING	
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。