

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/8/19	MAKE	CAT	MODEL	910K
SERIAL	CAT0910KVAY400872			STAMP	CAT0910KVAY400872
HR METER	7030	HR	Odometer	—	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	16.9-24

<table style="width: 100%;"> <tr> <td style="width: 50%;">ENGINE : MODEL</td> <td style="width: 50%;">S/N</td> </tr> <tr> <td>Oil leakage</td> <td>☒ FAIR · Attn</td> </tr> <tr> <td>Blow-By</td> <td>☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE</td> </tr> <tr> <td>Sound</td> <td>☒ FAIR · Attn</td> </tr> <tr> <td>Oil</td> <td>☒ FAIR · Attn</td> </tr> <tr> <td>Exhaust Color</td> <td>☒ FAIR · Attn</td> </tr> <tr> <td>US EPA</td> <td>☒ YES · NO</td> </tr> <tr> <td colspan="2">OPERATION PUMP</td> </tr> <tr> <td>Sound</td> <td>☒ FAIR · Attn</td> </tr> <tr> <td>Oil leakage</td> <td>☒ FAIR · Attn</td> </tr> <tr> <td>Power</td> <td>☒ FAIR · Attn</td> </tr> <tr> <td colspan="2">COOLING SYSTEM</td> </tr> <tr> <td>Radiator</td> <td>☒ FAIR · Attn</td> </tr> <tr> <td>Oil Cooler</td> <td>☒ FAIR · Attn</td> </tr> <tr> <td colspan="2">TRANSMISSION & TRAVEL</td> </tr> <tr> <td>T/M TYPE</td> <td>☒ PS · DD</td> </tr> <tr> <td>Transmission</td> <td>☒ FAIR · Attn</td> </tr> <tr> <td>Travel</td> <td>☒ FAIR · Attn</td> </tr> <tr> <td>FOOT BRAKE</td> <td>☒ FAIR · Attn</td> </tr> <tr> <td>PARKING BRAKE</td> <td>☒ FAIR · ☒ Attn 効かない MALFUNCTION</td> </tr> <tr> <td colspan="2">INTERIOR See Photos. 写真参照</td> </tr> <tr> <td>INTERIOR COND.</td> <td>CLEAN · ☒ FAIR · DIRTY</td> </tr> <tr> <td>Operator's Seat</td> <td>☒ FAIR · Attn</td> </tr> <tr> <td>Glasses</td> <td>☒ FAIR · Attn</td> </tr> <tr> <td>AirCon</td> <td>☒ A/C · H/C · H only · C only · None</td> </tr> <tr> <td colspan="2">FRONT & CYLINDERS</td> </tr> <tr> <td>Arm</td> <td>☒ FAIR · Attn ロングアーム LONG ARM</td> </tr> <tr> <td>Bell crank</td> <td>☒ FAIR · Attn</td> </tr> <tr> <td>Bucket</td> <td>☒ FAIR · ☒ Attn シリンダー油漏れ小 CYLINDER: OIL LEAKING</td> </tr> <tr> <td>Articulate</td> <td>☒ FAIR · Attn</td> </tr> </table>	ENGINE : MODEL	S/N	Oil leakage	☒ FAIR · Attn	Blow-By	☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE	Sound	☒ FAIR · Attn	Oil	☒ FAIR · Attn	Exhaust Color	☒ FAIR · Attn	US EPA	☒ YES · NO	OPERATION PUMP		Sound	☒ FAIR · Attn	Oil leakage	☒ FAIR · Attn	Power	☒ FAIR · Attn	COOLING SYSTEM		Radiator	☒ FAIR · Attn	Oil Cooler	☒ FAIR · Attn	TRANSMISSION & TRAVEL		T/M TYPE	☒ PS · DD	Transmission	☒ FAIR · Attn	Travel	☒ FAIR · Attn	FOOT BRAKE	☒ FAIR · Attn	PARKING BRAKE	☒ FAIR · ☒ Attn 効かない MALFUNCTION	INTERIOR See Photos. 写真参照		INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY	Operator's Seat	☒ FAIR · Attn	Glasses	☒ FAIR · Attn	AirCon	☒ A/C · H/C · H only · C only · None	FRONT & CYLINDERS		Arm	☒ FAIR · Attn ロングアーム LONG ARM	Bell crank	☒ FAIR · Attn	Bucket	☒ FAIR · ☒ Attn シリンダー油漏れ小 CYLINDER: OIL LEAKING	Articulate	☒ FAIR · Attn	<table style="width: 100%;"> <tr> <td colspan="2">UNDERCARRIAGE : See Photos. 写真参照</td> </tr> <tr> <td>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td>2</td> </tr> <tr> <td colspan="2">TIRE WEAR ☒ FAIR · WORN · UNEVEN WEAR</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2">STEERING TYPE ☒ WHEEL STEERING / ☒ COMMAND STEERING / LEVER STEERING</td> </tr> <tr> <td>RIDE CONTROL</td> <td>YES · ☒ NO</td> </tr> <tr> <td colspan="2">ATTACHMENTS</td> </tr> <tr> <td>STD BKT</td> <td>☒ YES · OTHER</td> </tr> <tr> <td>BLADE</td> <td>YES · ☒ NO Piping for Tilt YES · ☒ NO</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2">ラジエータフードヒンジ破損、フード外れあり</td> </tr> <tr> <td colspan="2">RADIATOR HOOD: COME OFF (RADIATOR HOOD HINGES: BROKEN)</td> </tr> <tr> <td colspan="2">A/C冷えない A/C: MALFUNCTION</td> </tr> <tr> <td colspan="2">RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> </tr> <tr> <td colspan="2">2</td> </tr> </table>	UNDERCARRIAGE : See Photos. 写真参照		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	TIRE WEAR ☒ FAIR · WORN · UNEVEN WEAR		COMMENT		STEERING TYPE ☒ WHEEL STEERING / ☒ COMMAND STEERING / LEVER STEERING		RIDE CONTROL	YES · ☒ NO	ATTACHMENTS		STD BKT	☒ YES · OTHER	BLADE	YES · ☒ NO Piping for Tilt YES · ☒ NO	COMMENT		ラジエータフードヒンジ破損、フード外れあり		RADIATOR HOOD: COME OFF (RADIATOR HOOD HINGES: BROKEN)		A/C冷えない A/C: MALFUNCTION		RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2	
ENGINE : MODEL	S/N																																																																																										
Oil leakage	☒ FAIR · Attn																																																																																										
Blow-By	☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE																																																																																										
Sound	☒ FAIR · Attn																																																																																										
Oil	☒ FAIR · Attn																																																																																										
Exhaust Color	☒ FAIR · Attn																																																																																										
US EPA	☒ YES · NO																																																																																										
OPERATION PUMP																																																																																											
Sound	☒ FAIR · Attn																																																																																										
Oil leakage	☒ FAIR · Attn																																																																																										
Power	☒ FAIR · Attn																																																																																										
COOLING SYSTEM																																																																																											
Radiator	☒ FAIR · Attn																																																																																										
Oil Cooler	☒ FAIR · Attn																																																																																										
TRANSMISSION & TRAVEL																																																																																											
T/M TYPE	☒ PS · DD																																																																																										
Transmission	☒ FAIR · Attn																																																																																										
Travel	☒ FAIR · Attn																																																																																										
FOOT BRAKE	☒ FAIR · Attn																																																																																										
PARKING BRAKE	☒ FAIR · ☒ Attn 効かない MALFUNCTION																																																																																										
INTERIOR See Photos. 写真参照																																																																																											
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY																																																																																										
Operator's Seat	☒ FAIR · Attn																																																																																										
Glasses	☒ FAIR · Attn																																																																																										
AirCon	☒ A/C · H/C · H only · C only · None																																																																																										
FRONT & CYLINDERS																																																																																											
Arm	☒ FAIR · Attn ロングアーム LONG ARM																																																																																										
Bell crank	☒ FAIR · Attn																																																																																										
Bucket	☒ FAIR · ☒ Attn シリンダー油漏れ小 CYLINDER: OIL LEAKING																																																																																										
Articulate	☒ FAIR · Attn																																																																																										
UNDERCARRIAGE : See Photos. 写真参照																																																																																											
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2																																																																																										
TIRE WEAR ☒ FAIR · WORN · UNEVEN WEAR																																																																																											
COMMENT																																																																																											
STEERING TYPE ☒ WHEEL STEERING / ☒ COMMAND STEERING / LEVER STEERING																																																																																											
RIDE CONTROL	YES · ☒ NO																																																																																										
ATTACHMENTS																																																																																											
STD BKT	☒ YES · OTHER																																																																																										
BLADE	YES · ☒ NO Piping for Tilt YES · ☒ NO																																																																																										
COMMENT																																																																																											
ラジエータフードヒンジ破損、フード外れあり																																																																																											
RADIATOR HOOD: COME OFF (RADIATOR HOOD HINGES: BROKEN)																																																																																											
A/C冷えない A/C: MALFUNCTION																																																																																											
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																																																																																											
2																																																																																											

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。