

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/19	MAKE	KUBOTA	MODEL	RX-306E
SERIAL	24087			STAMP	24087
HR METER	547	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	300R

ENGINE : MODEL		S/N	7JG2181
Oil leakage	☒ FAIR	Attn	
Blow-By	☒ FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR	Attn	
Oil	☒ FAIR	Attn	
Exhaust Color	☒ FAIR	Attn	
US EPA	YES	☒ NO	
MAIN PUMP			
Sound	☒ FAIR	Attn	
Oil leakage	☒ FAIR	Attn	
Power	☒ FAIR	Attn	
COOLING SYSTEM			
Radiator	☒ FAIR	Attn	
Oil Cooler	☒ FAIR	Attn	
OPERATING SYSTEM			
Swing	☒ FAIR	Attn	
Travel	☒ FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN	☒ FAIR	DIRTY
Operator's Seat	☒ FAIR	Attn	
Glasses	☒ FAIR	Attn	
AirCon	A/C	H/C	H only · C only · ☒ None
BOOM / ARM / BKT			
Boom	☒ FAIR	Attn	
Boom Cylinder	☒ FAIR	Attn	
Arm	☒ FAIR	Attn	
Arm Cylinder	☒ FAIR	Attn	
ATTACHMENT	☒ FAIR	Attn	
BKT Cylinder	☒ FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · ☒ WRIST
Multi	MULTI · ☒ 2 · NO
ARM-CRANE	☒ YES · NO
BLADE	☒ YES · NO
OFFSET	☒ YES · NO
OFFSET Cylinder	☒ FAIR · Attn
Piping	YES · ☒ NO Breaker only · Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。