

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/8/26	MAKE	CAT	MODEL	910-14A
SERIAL	CAT00910TJW201914			STAMP	CAT00910TJW201914
HR METER	925	HR	Odometer	1384	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	16.9-24

ENGINE : MODEL C3.6 S/N J3669286	UNDERCARRIAGE : See Photos. 写真参照	
Oil leakage ☒ FAIR · Attn	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 5	
Blow-By ☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE	TIRE WEAR ☒ FAIR · WORN · UNEVEN WEAR	
Sound ☒ FAIR · Attn	COMMENT	
Oil ☒ FAIR · Attn		
Exhaust Color ☒ FAIR · Attn		
US EPA ☒ YES · NO		
OPERATION PUMP		
Sound ☒ FAIR · Attn	STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING	
Oil leakage ☒ FAIR · Attn	RIDE CONTROL ☒ YES · NO	
Power ☒ FAIR · Attn	ATTACHMENTS	
COOLING SYSTEM		
Radiator ☒ FAIR · Attn	STD BKT ☒ YES · OTHER	
Oil Cooler ☒ FAIR · Attn	BLADE YES · ☒ NO Piping for Tilt ☒ YES · NO	
TRANSMISSION & TRAVEL		
T/M TYPE ☒ PS · DD	COMMENT	
Transmission ☒ FAIR · Attn		
Travel ☒ FAIR · Attn		
FOOT BRAKE ☒ FAIR · Attn		
PARKING BRAKE ☒ FAIR · Attn		
INTERIOR See Photos. 写真参照		
INTERIOR COND. ☒ CLEAN · FAIR · DIRTY		
Operator's Seat ☒ FAIR · Attn		
Glasses ☒ FAIR · Attn		
AirCon ☒ A/C · H/C · H only · C only · None		
FRONT & CYLINDERS		
Arm ☒ FAIR · Attn ロングアーム LONG ARM	RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 5	
Bell crank ☒ FAIR · Attn		
Bucket ☒ FAIR · Attn		
Articulate ☒ FAIR · Attn		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。