

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/25	MAKE	CAT	MODEL	311FLRR
SERIAL	CAT0311FLJFT10803		STAMP	CAT0311FLJFT10803	
HR METER	1170	HR	YEAR	YR	
CAB/CNP	☒ ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL C3.4B S/N CNW10921	
Oil leakage	☒ FAIR · Attn
Blow-By	☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn
Oil	☒ FAIR · Attn
Exhaust Color	☒ FAIR · Attn
US EPA	☒ YES · NO
MAIN PUMP	
Sound	☒ FAIR · Attn
Oil leakage	☒ FAIR · Attn
Power	☒ FAIR · Attn
COOLING SYSTEM	
Radiator	☒ FAIR · Attn
Oil Cooler	☒ FAIR · Attn
OPERATING SYSTEM	
Swing	☒ FAIR · Attn
Travel	☒ FAIR · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY
Operator's Seat	☒ FAIR · Attn
Glasses	☒ FAIR · Attn
AirCon	☒ A/C · H/C · H only · C only · None
BOOM / ARM / BKT	
Boom	☒ FAIR · Attn
Boom Cylinder	☒ FAIR · Attn
Arm	☒ FAIR · Attn ガタあり LOOSE
Arm Cylinder	☒ FAIR · Attn
ATTACHMENT	☒ FAIR · Attn
BKT Cylinder	☒ FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · ☒ WRIST
Multi	☒ MULTI · 2 · NO
ARM-CRANE	☒ YES · NO
BLADE	YES · ☒ NO
OFFSET	YES · ☒ NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · ☒ NO Breaker only · Multi
COMMENT	
ボディリペイントあり BODY: REPAINTED	
A/C風出ない(ブロアモーター不良)	
A/C: NOT BLOWING AIR (BLOWER MOTOR: MALFUNCTION)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。