

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/24	MAKE	CAT	MODEL	308E2SR-E
SERIAL	CAT0308EVKC500270			STAMP	CAT0308EVKC500270
HR METER	2375	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	450G PADS

ENGINE : MODEL		C3.3B	S/N
Oil leakage	(FAIR) · Attn		
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	(FAIR) · Attn		
Oil	(FAIR) · Attn		
Exhaust Color	(FAIR) · Attn		
US EPA	(YES) · NO		
MAIN PUMP			
Sound	(FAIR) · Attn		
Oil leakage	(FAIR) · Attn		
Power	(FAIR) · Attn		
COOLING SYSTEM			
Radiator	(FAIR) · Attn		
Oil Cooler	(FAIR) · Attn		
OPERATING SYSTEM			
Swing	(FAIR) · Attn	ガタあり SWING: LOOSE	
Travel	(FAIR) · Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · (FAIR) · DIRTY		
Operator's Seat	(FAIR) · Attn		
Glasses	(FAIR) · Attn		
AirCon	(A/C) · H/C · H only · C only · None		
BOOM / ARM / BKT			
Boom	(FAIR) · Attn		
Boom Cylinder	(FAIR) · Attn		
Arm	(FAIR) · Attn		
Arm Cylinder	(FAIR) · Attn		
ATTACHMENT	(FAIR) · Attn		
BKT Cylinder	(FAIR) · Attn		

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4
COMMENT			
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER()		
Lever	LONG · (WRIST)		
Multi	(MULTI) · 2 · NO		
ARM-CRANE	(YES) · NO		
BLADE	(YES) · NO		
OFFSET	(YES) · NO		
OFFSET Cylinder	(FAIR) · Attn		
Piping	YES · (NO)	Breaker only · Multi	
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。