

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |      |       |                   |
|-----------------|----------------------------------------|------|------|-------|-------------------|
| INSPECTION DATE | 2026/8/20                              | MAKE | CAT  | MODEL | 308CR-07A         |
| SERIAL          | CAT00308TGX801727                      |      |      | STAMP | CAT00308TGX801727 |
| HR METER        | 6108                                   | HR   | YEAR | YR    |                   |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      |      | SHOE  | 450G PADS         |

|                                  |                                           |                            |
|----------------------------------|-------------------------------------------|----------------------------|
| <b>ENGINE : MODEL</b>            |                                           | <b>S/N</b>                 |
| Oil leakage                      | FAIR • <u>Attn</u>                        | 油汚れ大 MUCH OIL STAINS       |
| Blow-By                          | FAIR • Attn                               | A LITTLE • MIDDLE • SEVERE |
| Sound                            | <u>FAIR</u> • Attn                        |                            |
| Oil                              | <u>FAIR</u> • Attn                        |                            |
| Exhaust Color                    | <u>FAIR</u> • Attn                        |                            |
| US EPA                           | YES • <u>NO</u>                           |                            |
| <b>MAIN PUMP</b>                 |                                           |                            |
| Sound                            | <u>FAIR</u> • Attn                        |                            |
| Oil leakage                      | <u>FAIR</u> • Attn                        |                            |
| Power                            | <u>FAIR</u> • Attn                        |                            |
| <b>COOLING SYSTEM</b>            |                                           |                            |
| Radiator                         | <u>FAIR</u> • Attn                        |                            |
| Oil Cooler                       | <u>FAIR</u> • Attn                        |                            |
| <b>OPERATING SYSTEM</b>          |                                           |                            |
| Swing                            | <u>FAIR</u> • Attn                        |                            |
| Travel                           | <u>FAIR</u> • Attn                        |                            |
| <b>INTERIOR See Photos. 写真参照</b> |                                           |                            |
| INTERIOR COND.                   | CLEAN • <u>FAIR</u> • DIRTY               |                            |
| Operator's Seat                  | <u>FAIR</u> • Attn                        |                            |
| Glasses                          | <u>FAIR</u> • Attn                        |                            |
| AirCon                           | <u>A/C</u> • H/C • H only • C only • None |                            |
| <b>BOOM / ARM / BKT</b>          |                                           |                            |
| Boom                             | <u>FAIR</u> • Attn                        |                            |
| Boom Cylinder                    | <u>FAIR</u> • Attn                        |                            |
| Arm                              | <u>FAIR</u> • Attn                        |                            |
| Arm Cylinder                     | <u>FAIR</u> • Attn                        |                            |
| ATTACHMENT                       | <u>FAIR</u> • Attn                        |                            |
| BKT Cylinder                     | <u>FAIR</u> • Attn                        |                            |

|                                                                      |                                                    |
|----------------------------------------------------------------------|----------------------------------------------------|
| <b>UNDERCARRIAGE : See Photos. 写真参照</b>                              |                                                    |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         | 4                                                  |
| <b>COMMENT</b>                                                       |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
| BKT                                                                  | <u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ( ) |
| Lever                                                                | LONG • <u>WRIST</u>                                |
| Multi                                                                | <u>MULTI</u> • 2 • NO                              |
| ARM-CRANE                                                            | YES • <u>NO</u>                                    |
| BLADE                                                                | YES • <u>NO</u>                                    |
| OFFSET                                                               | YES • <u>NO</u>                                    |
| OFFSET Cylinder                                                      | FAIR • Attn                                        |
| Piping                                                               | <u>YES</u> • NO Breaker only • <u>Multi</u>        |
| <b>COMMENT</b>                                                       |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) |                                                    |
| 4                                                                    |                                                    |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。