

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/26	MAKE	KOBELCO	MODEL	SK120
SERIAL	NO PLATE			STAMP	LP-09953
HR METER	2901	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	700G

ENGINE : MODEL		S/N	221192
Oil leakage	FAIR · ☒ Attn	*1	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · ☒ NO		
MAIN PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
OPERATING SYSTEM			
Swing	FAIR · Attn		
Travel	FAIR · Attn	*2	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR · ☒ DIRTY		
Operator's Seat	FAIR · ☒ Attn	破れ大 MUCH TORN	
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · None		
BOOM / ARM / BKT			
Boom	FAIR · Attn		
Boom Cylinder	FAIR · ☒ Attn	*3	
Arm	FAIR · Attn	パッチ多数あり MUCH PATCHED	
Arm Cylinder	FAIR · ☒ Attn	*4	
ATTACHMENT	FAIR · Attn		
BKT Cylinder	FAIR · Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · ☒ WRIST
Multi	☒ MULTI · 2 · NO
ARM-CRANE	YES · ☒ NO
BLADE	YES · ☒ NO
OFFSET	YES · ☒ NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · ☒ NO Breaker only · Multi
COMMENT	
後付けA/Cあり	
W/RETROFITTED A/C (ORIGINAL A/C: MALFUNCTION)	
機体外装リペイントあり REPAINTED	
下周り油漏れあり BOTTOM: OIL LEAKING	
アクセルレバー固い ACCELERATOR LEVER: STIFF	
*1 クランクシール油漏れあり OIL LEAKING	
*2 ローのまま切替らない UNABLE TO SWITCH TO HIGH GEAR	
*3 左右シリンダー油漏れあり(吸着マットあり)	
*3 CYLINDERS: OIL LEAKING (W/ABSORPTION MAT)	
*4 にじみあり(吸着マットあり) OIL OOOZING (W/ABSORPTION MAT)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。