

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/8/25	MAKE	KATO	MODEL	KR-25H-V7
SERIAL No.	PLATE : 5110219		STAMP : KRC005-0219		
HR METER	25145	HR	Odometer	119799	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL	S/N
Oil leakage	FAIR · Attn
Blow-By	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn

OPERATION PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn

COOLING SYSTEM		
Radiator	FAIR - Attn	
Oil Cooler	FAIR - Attn	

OPERATING SYSTEM		
Computer	OK・NG	F96エラー表示あり “F96” ERROR DISPLAY
Swing	FAIR・Attn	
Travel	FAIR・Attn	

TRANSMISSION		
Transmission	FAIR • Attn	
No. OF GEARS	4	GEARS
4WD	4WD • 6WD	

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN	FAIR
Operator's Seat	FAIR	Attn
Glasses	FAIR	Attn
AirCon	A/C	H/C
	H only	C only
	None	

COMMENT

BOOM		
No. of Section	4	SECTIONS
CRACK/ENFORCEMENT	☐ FAIR ▪ Attn	
DERRICKING CYL.	☐ FAIR ▪ Attn	
EXTENSION CYL.	☐ FAIR ▪ Attn	
JIB	☐ YES ▪ NO	
JIB TYPE	STD ▪ ☐ PWR	
MAIN & SUB WIRE	☐ YES ▪ NO	
FREE FALL	YES ▪ ☐ NO	
HOOK	25t, BALL	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	FAIR • WORN <u>UNEVEN WEAR</u>

COMMENT	

OUTRIGGERS				
OUTRIGGERS	X	•	H	
OUTRIGGERS COND.	FAIR	•	Attn	
Oil leakage (JACK CYL.)	FRONT	L	• R	REAR L • R
Oil leakage (SLIDE CYL.)	FRONT	L	• R	REAR L • R

COMMENT	
リターダー油漏れあり RETARDER: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。