

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/8/20	MAKE	KATO	MODEL	KR-25H-V5
SERIAL No.	PLATE : 5413073			STAMP : KR258-3073	
HR METER	34925	HR	Odometer	62708	km
TIRE SIZE	385/95R25			YEAR	YR

ENGINE : MODEL		S/N
Oil leakage	FAIR ☐ Attn	下部にじみあり BOTTOM OF ENGINE: OIL OOZING
Blow-By	FAIR ☐ Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR ☐ Attn	
Oil	FAIR ☐ Attn	
Exhaust Color	FAIR ☐ Attn	白煙あり WHITE FUMES
OPERATION PUMP		
Sound	FAIR ☐ Attn	
Oil leakage	FAIR ☐ Attn	
Power	FAIR ☐ Attn	
COOLING SYSTEM		
Radiator	FAIR ☐ Attn	
Oil Cooler	FAIR ☐ Attn	
OPERATING SYSTEM		
Computer	OK ☐ NG	
Swing	FAIR ☐ Attn	
Travel	FAIR ☐ Attn	
TRANSMISSION		
Transmission	FAIR ☐ Attn	
No. OF GEARS	4 GEARS	
4WD	4WD ☐ 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR ☐ Attn	
Glasses	FAIR ☐ Attn	
AirCon	A/C ☐ H/C · H only · C only · None	
COMMENT		

BOOM					
No. of Section	4	SECTIONS			
CRACK/ENFORCEMENT	FAIR ☐ Attn				
DERRICKING CYL.	FAIR ☐ Attn				
EXTENSION CYL.	FAIR ☐ Attn				
JIB	YES ☐ NO				
JIB TYPE	STD ☐ PWR				
MAIN & SUB WIRE	YES ☐ NO				
FREE FALL	YES ☐ NO				
HOOK	25t, BALL				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					1
TIRE WEAR	FAIR ☐ WORN · UNEVEN WEAR				
COMMENT					
タイヤ4本側面亀裂あり、自走不可					
TIRE SIDEWALLS: CRACKED (UNABLE TO RUN ON PUBLIC ROADS)					
OUTRIGGERS					
OUTRIGGERS	X ☐ H				
OUTRIGGERS COND.	FAIR ☐ Attn	*1			
Oil leakage (JACK CYL.)	FRONT	L · R	REAR	L · R	
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR	L · R	
COMMENT					
フェンダー穴あり FENDERS: HUGE HOLES					
A/Cモーター付近油漏れあり AROUND A/C MOTOR: OIL LEAKING					
*1 左R縦シリンダーロッド傷あり					
*1 REAR LEFT JACK CYLINDER ROD: SCRATCHED					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。