

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/8/21	MAKE	TADANO	MODEL	TR-200M-5
SERIAL No.	PLATE :	521973	STAMP :	TR203-0070	
HR METER	9038	HR	Odometer	79083	km
TIRE SIZE	385/95R25	YEAR	YR		

ENGINE : MODEL		S/N
Oil leakage	FAIR ☒ Attn	*1
Blow-By	FAIR ☒ Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR ☒ Attn	
Oil	FAIR ☒ Attn	
Exhaust Color	FAIR ☒ Attn	
OPERATION PUMP		
Sound	FAIR ☒ Attn	
Oil leakage	FAIR ☒ Attn	
Power	FAIR ☒ Attn	
COOLING SYSTEM		
Radiator	FAIR ☒ Attn	
Oil Cooler	FAIR ☒ Attn	
OPERATING SYSTEM		
Computer	OK ☒ NG	
Swing	FAIR ☒ Attn	
Travel	FAIR ☒ Attn	
TRANSMISSION		
Transmission	FAIR ☒ Attn	
No. OF GEARS	4 GEARS	
4WD	4WD ☒ 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR ☒ DIRTY	
Operator's Seat	FAIR ☒ Attn	
Glasses	FAIR ☒ Attn	
AirCon	A/C ☒ H/C · H only · C only · None	
COMMENT		

BOOM					
No. of Section	6	SECTIONS			
CRACK/ENFORCEMENT	FAIR ☒ Attn				
DERRICKING CYL.	FAIR ☒ Attn				
EXTENSION CYL.	FAIR ☒ Attn				
JIB	YES ☒ NO				
JIB TYPE	STD ☒ PWR				
MAIN & SUB WIRE	YES ☒ NO	*2			
FREE FALL	YES ☒ NO				
HOOK	20t, BALL				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					2
TIRE WEAR	FAIR ☒ WORN ☒ UNEVEN WEAR				
COMMENT					
右Rタイヤサイド亀裂あり REAR RIGHT TIRE SIDEWALL: CRACKED					
OUTRIGGERS					
OUTRIGGERS	X ☒ H				
OUTRIGGERS COND.	FAIR ☒ Attn	*3			
Oil leakage (JACK CYL.)	FRONT	L · R	REAR	L · R	
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR	L · R	
COMMENT					
シングルトップ損傷あり(別置き) SINGLE TOP: DAMAGED, NOT ATTACHED					
ボールフック別置き BALL HOOK: NOT ATTACHED					
*1 E/G下部油漏れあり BOTTOM OF ENGINE: OIL LEAKING					
*2 補巻ワイヤー外れあり AUXILIARY HOISTING WIRE: COME OFF					
*3 左Fアウトリガー皿曲がりあり FRONT LEFT FLOAT: DISTORTED					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。