

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/8/25	MAKE	KOMATSU	MODEL	WA450-3E
SERIAL	53200	STAMP	W035-53200		
HR METER	31733	HR	Odometer	-	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	TIRE SIZE	23.5-25 20PR	YEAR	1998 YR

ENGINE : MODEL		S/N
Oil leakage	FAIR	Attn
Blow-By	FAIR	Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn
Oil	FAIR	Attn
Exhaust Color	FAIR	Attn
US EPA	YES	NO
OPERATION PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn
COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn
TRANSMISSION & TRAVEL		
T/M TYPE	PS	DD
Transmission	FAIR	Attn *1
Travel	FAIR	Attn
FOOT BRAKE	FAIR	Attn
PARKING BRAKE	FAIR	Attn
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR ·	DIRTY
Operator's Seat	FAIR	Attn 破れあり CUTS
Glasses	FAIR	Attn
AirCon	A/C · H/C ·	H only · C only · None
FRONT & CYLINDERS		
Arm	FAIR	Attn
Bell crank	FAIR	Attn
Bucket	FAIR	Attn ボトム側ガタあり BOTTOM SIDE: LOOSE
Articulate	FAIR	Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT	
下周り油漏れあり(吸着マットあり)	
BOTTOM: OIL LEAKING (W/ABSORPTION MAT)	
STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	YES · NO
ATTACHMENTS	
STD BKT	YES · OTHER
BLADE	YES · NO Piping for Tilt YES · NO *2
COMMENT	
A/C故障あり A/C: MALFUNCTION	
作動油タンクにじみあり HYDRAULIC OIL TANK: OIL OOZING	
コントロールバルブ付近油漏れあり(吸着マットあり)	
AROUND CONTROL VALVE: OIL LEAKING (W/ABSORPTION MAT)	
Pランプ点灯しない PARKING LAMP: UNABLE TO LIGHT ON	
*1 ポンプにじみあり(吸着マットあり)	
*1 TRANSMISSION OIL PUMP: OIL OOZING (W/ABSORPTION MAT)	
*2 ホース欠 HOSES: MISSING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。