

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/8/21	MAKE	TADANO	MODEL	GR-120N-1
SERIAL No.	PLATE : FD0618		STAMP : TR120-0618		
HR METER	10875	HR	Odometer	110895	km
TIRE SIZE	275/80R22.5		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	
Blow-By	☒ FAIR · ☒ Attn	A LITTLE · MIDDLE · ☒ SEVERE
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · ☒ Attn	白煙大 MUCH WHITE FUMES
OPERATION PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · ☒ Attn	*1
COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	
OPERATING SYSTEM		
Computer	☒ OK · NG	
Swing	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	
TRANSMISSION		
Transmission	☒ FAIR · Attn	
No. OF GEARS	3	GEARS
4WD	☒ 4WD · 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · ☒ FAIR ·	DIRTY
Operator's Seat	☒ FAIR · Attn	
Glasses	☒ FAIR · Attn	
AirCon	☒ A/C · H/C · H only · C only · None	
COMMENT		

BOOM					
No. of Section	6	SECTIONS			
CRACK/ENFORCEMENT	☒ FAIR · Attn				
DERRICKING CYL.	☒ FAIR · Attn				
EXTENSION CYL.	☒ FAIR · Attn				
JIB	☒ YES · NO				
JIB TYPE	STD · ☒ PWR				
MAIN & SUB WIRE	☒ YES · NO				
FREE FALL	YES · ☒ NO				
HOOK	12t, BALL				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)					3
TIRE WEAR	FAIR · ☒ WORN ·	UNEVEN WEAR			
COMMENT					
OUTRIGGERS					
OUTRIGGERS	X · ☒ H				
OUTRIGGERS COND.	FAIR · ☒ Attn	*2			
Oil leakage (JACK CYL.)	FRONT	L · R	REAR	L · R	
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR	L · R	
COMMENT					
*1 クレーン操作時、走行時に負荷を掛けるとE/Gダウンする(自走不可)					
*1 ENGINE STALLING WITH ENGINE LOAD INCREASING					
WHEN OPERATING CRANE or TRAVELING					
(UNABLE TO RUN ON PUBLIC ROADS)					
*2 右R縦シリンダーにじみあり					
*2 REAR RIGHT JACK CYLINDER: OIL OOZING					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。