

INSPECTION SHEET 検品書
MOTOR GRADER グレーダー

INSPECTION DATE	2026/8/26	MAKE	KOMATSU	MODEL	GH320-2E
SERIAL	12043	STAMP	GH3202-12043		
HR METER	8191	HR	Odometer	-	km
YEAR		YR			
SCARIFIER	YES	NO	BLADE	4360	mm
CAB/CNP	CAB	CNP	NONE	TIRE SIZE	14.00-24 20PR (SNOW, SPIKE)

ENGINE : MODEL	6D125E-2	S/N	81025	UNDERCARRIAGE :	See Photos. 写真参照
Oil leakage	FAIR	Attn		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	TIRE WEAR	FAIR · WORN · UNEVEN WEAR
Sound	FAIR	Attn		COMMENT	
Oil	FAIR	Attn			タコメーター TACHOMETER: 67570km
Exhaust Color	FAIR	Attn			機体外装リペイントあり REPAINTED
US EPA	YES	NO			左タイヤ真ん中傷あり FRONT ONE OF REAR TIRES: HUGE CUT
OPERATION PUMP					左フェンダー変形あり REAR LEFT FENDER: DEFORMED
Sound	FAIR	Attn			左ドア閉まらない LEFT DOOR: UNABLE TO SHUT
Oil leakage	FAIR	Attn			
Power	FAIR	Attn			
COOLING SYSTEM					
Radiator	FAIR	Attn			
Oil Cooler	FAIR	Attn			
TRANSMISSION & TRAVEL					
T/M TYPE	PS	DD			
Transmission	FAIR	Attn			
Travel	FAIR	Attn	6・7速未確認 6th & 7th GEARS: NOT CHECKED		
FOOT BRAKE	FAIR	Attn			
PARKING BRAKE	FAIR	Attn			
INTERIOR	See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY		
Operator's Seat	FAIR	Attn			
Glasses	FAIR	Attn			
AirCon	A/C	H/C	H only	C only	None
HYD. CYLINDER					
For Blade	FAIR	Attn			
For Scarifier	FAIR	Attn			
Articulate	FAIR	Attn			
				RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。