

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/24	MAKE	KOBELCO	MODEL	SK115SR-1ES
SERIAL	YV04-03373			STAMP	YV04-03373
HR METER	7655	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	500G

ENGINE : MODEL		4BG1	S/N	916780
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn	ガタ小 SWING: LOOSE	
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn	破れ小 HOLES	
Glasses	FAIR	Attn	*1	
AirCon	A/C	H/C	H only	C only · None
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn	*2	
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn	油漏れ小 OIL LEAKING	
ATTACHMENT	FAIR	Attn	ピンガタ大 PIN: MUCH LOOSE	
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
COMMENT	
燃料メーター故障、液晶画面故障あり	
FUEL GAUGE & MONITOR: MALFUNCTION	
A/C効かない A/C: MALFUNCTION	
*1 ドア下部、F下部、右側面アクリル板で補修あり(ガムテープで固定あり)	
*1 LOWER DOOR GLASS, LOWER WINDSHIELD, & RIGHT SIDE GLASS:	
ACRYLIC BOARDS (FIXED WITH ADHESIVE TAPES)	
*2 左油漏れあり、右油漏れ小 CYLINDERS: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。