

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/8/28	MAKE	HITACHI	MODEL	ZX50U-5B
SERIAL	HMAEJA0V00060685		STAMP	HMAEJA0V00060685	
HR METER	2811	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	400R	

ENGINE : MODEL 4TNV88C S/N 42431					
Oil leakage	(FAIR)	Attn			
Blow-By	(FAIR)	Attn	A LITTLE	MIDDLE	SEVERE
Sound	(FAIR)	Attn			
Oil	(FAIR)	Attn			
Exhaust Color	(FAIR)	Attn			
US EPA	YES	(NO)			
MAIN PUMP					
Sound	(FAIR)	Attn			
Oil leakage	(FAIR)	Attn			
Power	(FAIR)	Attn			
COOLING SYSTEM					
Radiator	(FAIR)	Attn			
Oil Cooler	(FAIR)	Attn			
OPERATING SYSTEM					
Swing	(FAIR)	Attn			
Travel	(FAIR)	Attn			
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN	(FAIR)	DIRTY		
Operator's Seat	(FAIR)	Attn			
Glasses	FAIR	Attn			
AirCon	A/C	H/C	H only	C only	(None)
BOOM / ARM / BKT					
Boom	(FAIR)	Attn			
Boom Cylinder	(FAIR)	Attn			
Arm	(FAIR)	Attn			
Arm Cylinder	(FAIR)	Attn			
ATTACHMENT	(FAIR)	Attn			
BKT Cylinder	(FAIR)	Attn			
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
COMMENT シュー切れあり RUBBER TRACKS: CUTS					
BKT (STD / SLOPE / NARROW / SKELETON / OTHER()					
Lever	LONG	(WRIST)			
Multi	(MULTI)	2	NO		
ARM-CRANE	(YES)	NO			
BLADE	(YES)	NO			
OFFSET	YES	(NO)			
OFFSET Cylinder	FAIR	Attn			
Piping	YES	(NO)	Breaker only	Multi	
COMMENT					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3					

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。