

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/8/24	MAKE	CAT	MODEL	938G
SERIAL	CAT0938GP8RS01234			STAMP	CAT0938GP8RS001234
HR METER	UNKNOWN	HR	Odometer	—	km
				YEAR	2002 YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	23.5-25

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	
US EPA	YES · ☒ NO	
OPERATION PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	
COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	☒ PS · DD	
Transmission	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	
FOOT BRAKE	☒ FAIR · Attn	
PARKING BRAKE	☒ FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · ☒ DIRTY	
Operator's Seat	☒ FAIR · Attn	破れ大 A LITTLE DAMAGED
Glasses	☒ FAIR · Attn	
AirCon	☒ A/C · H/C · H only · C only · None	
FRONT & CYLINDERS		
Arm	☒ FAIR · Attn	
Bell crank	☒ FAIR · Attn	
Bucket	☒ FAIR · Attn	
Articulate	☒ FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	FAIR · WORN · ☒ UNEVEN WEAR
COMMENT	
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING	
RIDE CONTROL	YES · ☒ NO
ATTACHMENTS	
STD BKT	☒ YES · OTHER
BLADE	YES · ☒ NO Piping for Tilt YES · ☒ NO
COMMENT	
ボディリペイントあり BODY: REPAINTED	
A/Cベルト欠 A/C: NO BELT	
HRメーター不良 HR METER: MALFUNCTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。